

SWAN FARM MACHINERY NEWSLETTER

EDITION FOURTEEN – 23/12/2011

Bevan - bevan@swanfm.com.au Owen - owen@swanfm.com.au Geoff - sales@swanfm.com.au

Hawk - admin@swanfm.com.au Laura / Andrew - parts@swanfm.com.au

www.swanfm.com.au

WELCOME TO 2012!

HOT OFFERS ON NEW MACHINERY

SPRAYING - Have you been thinking about upgrading your boom spray? We currently have a machine in stock and can talk to you about your spraying requirements.

TILLAGE – Act now if you still require new machinery for this coming season. Time is running out to be able to get new machines in time!

NEW HOLLAND 3D DEALS – Super Deal out from New Holland on Tractors (excluding compact range)

- Interest rate from 3 %
- 3 Years Warranty
- Offer only available for 3 months (Jan – Mar 2012)

ACT NOW! TALK TO BEVAN OR GEOFF ABOUT THIS TODAY!



SWAN FARM MACHINERY WEBSITE UPGRADED!

When you are surfing the net, pop over and have a look at our upgraded website

www.swanfm.com.au

It contains links to all our major products, used machinery, online New Holland parts and many other handy links.



FREIGHT FREE PARTS ORDERING!

Did you know we place a stock order with both New Holland and Hardi on a weekly basis (provided minimum requirements met)? The New Holland order takes approx 1 working week to arrive and the Hardi order is in store Wednesday of the following week. Best of all – if you order parts on a weekly stock order – it will be **FREIGHT FREE!** These orders are perfect for ordering repair parts for your machines before you put them away in the shed for next season!

OWEN'S WORKSHOP TIP OF THE WEEK

As you all start your summer spraying, it is a perfect time to think about calibrating your nozzles to ensure you are getting the most from your sprayer.

- Jug test your current nozzle for 1 minute, taking note of the bar that you are testing at
- Jug test a brand new nozzle at the same bar
- Compare the results between the 2 nozzles
- Have a look at the attached application rate table and see the l/min rate you should have got based on nozzle and bar.

If you have a machine with sections, a test should ideally be done on each section.

If you're current nozzle is releasing 8 – 10% or higher than the new nozzle it is recommended to replace the complete set.



SPECIAL OFFER – BUY A COMPLETE SET OF NOZZLES FOR YOUR MACHINE IN JANUARY AND GET 5% OFF

